Green River Knoll
Teton Range
WY
Elevation: 9800 ft
Aspect: S
Specifics: Poor pit location

Brenden Cronin
01/06/2017 - 10:00am
Co-ord:
Slope Angle: 32°
Wind Loading: previous

Stability: Good
Air Temperature: -12°F
Sky Cover: CLR
Precipitation: NO
Wind: W Light Breeze

HS: 160
PS: 20

Layer Notes:
143-105cm: Problematic layer



Notes: This may have been a poor pit site due to previous loading and lack of a defined sun crust on a S aspect. The layers at 95cm and 65cm may be old sun crust the have sublin
Pit was not dug to ground.
Total height of snow: 210cm