W or Mrror Lk Hghwy2
Uinta Range
UT
Elevation: 9700 ft
Aspect: 320°

Mark Staples
01/07/2017 - 2:00pm
Co-ord: 40.68689N, -111.11329W
Slope Angle: 18°
Wind Loading:

Stability: Good
Air Temperature:
Sky Cover: BKN
Precipitation: NO
Wind:

HS: 130

Layer Notes:
105-100cm: Problematic layer

Specifics: Snowmobile tracks on slope; We snowmobiled slope



Notes: Surface hoar was an obvious stripe. It was buried on Jan 2 for reference. I'm not sure why it didn't propagate in tests. There was no cracking observed on any layer during slope cuts and other informal tests.