Miller Road
Beartooths
MT
Elevation: 9300 ft
Aspect: 230°
Specifics: Cracking

Doug Chabot-Admin
01/10/2017 - 1:00pm
Co-ord: 45.04972N, -109.95046W
Slope Angle: 33°
Wind Loading: yes

Stability: Very Poor
Air Temperature: -5°C
Sky Cover: OVC
Precipitation: S2
Wind: SW Moderate

HS: 170

Layer Notes:
52-52.5cm: Problematic layer



Notes: PST had a high score because it was difficult to keep the saw in the weak layer (I think). Visibility was poor so I could not tell if there were many naturals. Avalanche Warning in effect.