2017-01-12 Bjøberg
Hemsedalsfjellet
Norway
Elevation:
Aspect:

Aanon Clausen
12/01/2017 - 01:00
Co-ord:
Slope Angle:
Wind Loading: yes

Stability: Fair
Air Temperature: -4°C
Sky Cover: FEW
Precipitation: S-1
Wind: W Moderate

Layer Notes:
15-17cm: Problematic layer

Specifics: Cracking; Recent avalanche activity on similar slopes; We skied slope



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
●	0.5			
/	1			← ECTP11 @16cm Thin slab CT1, Q2 @16cm Top layer, small sla
♡		D		

Notes: Heavy previous windloading, moderate current windloading