NO Ramundberget
Funäsfjällen
Sweden
Elevation: 1000 m
Aspect: NE
Specifics: Collapsing, localized; Poor pit location

John Wilcoxen
23/12/2018 - 00:30
Co-ord: 62.68552N, 12.36115E
Slope Angle: 19°
Wind Loading: no

Stability: Fair
Air Temperature: -9.1°C
Sky Cover: CLR
Precipitation: NO
Wind: NE Light Breeze

HS: 65

Layer Notes:
29-0cm: Problematic layer



Notes: