Targhee Pass Meadows
Henry Mtns
MT
Elevation: 8230 ft
Aspect: 30°
Specifics: Collapsing, localized; Cracking

Andrew Schauer
12/08/2019 - 12:00pm
Co-ord: 44.68610N, -111.29080W
Slope Angle: 28°
Wind Loading: yes

Stability: Very Poor
Air Temperature:
Sky Cover: OVC
Precipitation: S2
Wind: SW Moderate

HS: 76
PF: 60
PS: 20

Layer Notes:
32-15cm: Problematic layer



Notes: Profile at fracture line of a slab that collapsed in DH layer (15-32cm) and propagated ~100'.