Southern Missions
Missions
MT
Elevation: 6100 ft
Aspect: 280°
Specifics: Collapsing, localized; Cracking

Travis Craft
12/09/2019 - 1:50pm
Co-ord:
Slope Angle: 27°
Wind Loading: no

Stability:
Air Temperature: -7°C
Sky Cover: OVC
Precipitation: S-1
Wind: NW Calm

HS: 66
PF: 40
PS: 20

Layer Notes:
42.3-42.1cm: Problematic layer





Notes: