Upper Senator Beck
San Juan Range
CO
Elevation: 12924 ft
Aspect: NE
Specifics:

Bill Nalli
12/23/2019 - 3:00pm
Co-ord: 37.91468N, -107.73207W
Slope Angle: 30°
Wind Loading: yes

Stability: Good
Air Temperature: -6°C
Sky Cover: OVC
Precipitation: NO
Wind: SW Moderate

HS: 160
PF: 15
PS: 5

Layer Notes:
15-0cm: Problematic layer



Notes: This test slope location is deep and may not be completelty representative of HS throughout the basin. It does provide a good example of a deep strong slab with old October snow continuing to strengthen and round. It would take a massive load to break this slab and create an avalanche.