MayflowerAIARE1
Vail/Summit County
CO
Elevation: 11700 ft
Aspect: 288°
Specifics:

Dave Capasso
12/04/2016 - 12:00pm
Co-ord:
Slope Angle: 13°
Wind Loading: yes

Stability:
Air Temperature:
Sky Cover: FEW
Precipitation: NO
Wind: Moderate

HS: 34

Layer Notes:
20.5-19cm: Problematic layer



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
				←CT18, PC @19cm RP/PC

Notes: Temp and Grain n/o