Mahanga WP
Nelson Lakes
New Zealand
Elevation: 1962 m
Aspect: 225°
Specifics: Poor pit location

Seán Mulvany
28/07/2020 - 12:28
Co-ord:
Slope Angle: 34°
Wind Loading:

Stability:
Air Temperature: -2°C
Sky Cover: SCT
Precipitation: NO
Wind: N Light Breeze

HS: 130
PF: 23

Layer Notes:
76-63cm: Problematic layer



Notes: