grease bucket
Whakapapa
New Zealand
Elevation: 2006 m
Aspect: SE

matiu kapa
05/10/2020 - 15:00
Co-ord: 12U 376152W 5654190N
Slope Angle: 37°
Wind Loading: no

Stability: Fair
Air Temperature: 10.7°C
Sky Cover: CLR
Precipitation: NO
Wind: S Light Breeze

PF: 30
PS: 5

Layer Notes:

Specifics: Pit dug in a Ski Area; Recent avalanche activity on similar slopes; Instability rapidly rising



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
			470	
			470	
O	2-2.5	V		
				ECTX

Notes: