Sunlight Basin
Madison Range-S
MT
Elevation: 9426 ft
Aspect: 110°

Dave Zinn
12/21/2020 - 1:00pm
Co-ord: 44.97491N, -111.31356W
Slope Angle: 23°
Wind Loading: previous

Stability: Poor
Air Temperature: -7°C
Sky Cover: BKN
Precipitation: NO
Wind: SW Strong

HS: 107
PF: 45

Layer Notes:
60-50cm: Problematic layer
50-36cm: Dirty - wind blown dust

Specifics: Pit is adjacent to avalanche: other; Collapsing, localized; Recent avalanche activity on similar slopes; Recent avalanche activity on different slopes



Depth	Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
107					
100					
90					
80					
70					
60	□ (∧)	2-3 (3)			ECTP9 @60cm; ECTP11 @60cm
50	□ (∧)	2-3 (3)			50-36cm: Dirty - wind blown dust
40					
30	□	2			
20	⊖	2			
10	■				
0					

Notes: