Gladstones
San Juan Range
CO
Elevation: 9551 ft
Aspect: 30°
Specifics: Collapsing, localized

Colin Mitchell
12/14/2021 - 1:00pm
Co-ord: 37.80411N, -107.67990W
Slope Angle: 20°
Wind Loading:

Stability: Fair
Air Temperature: -1°C
Sky Cover: OVC
Precipitation: NO
Wind: S Light Breeze

HS: 45
PF: 40

Layer Notes:
9.5-0cm: Problematic layer



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
●		D		
◎◎		D		←ECTP13 @9.5cm
^	3-5	D		

Notes: