Carbon
San Juan Range
CO
Elevation: 11405 ft
Aspect: 110°
Specifics: Collapsing, widespread; Cracking

Ann Mellick
12/15/2021 - 12:00pm
Co-ord: 37.88943N, -107.70932W
Slope Angle: 29°
Wind Loading: yes

Stability:
Air Temperature: -10°C
Sky Cover: OVC
Precipitation: S2
Wind: N Moderate

HS: 100
PF: 50
PS: 15

Layer Notes:
24-20cm: Problematic layer



Notes: