Hasty Diamond Face
Vail/Summit County
CO
Elevation: 12031 ft
Aspect: 110°
Specifics: Pit dug in a Ski Area

Matt Urich
02/19/2022 - 2:15pm
Co-ord: 39.45512N, -106.16818E
Slope Angle: 36°
Wind Loading: no

Stability:
Air Temperature:
Sky Cover: CLR
Precipitation: NO
Wind: W Light Breeze

HS: 114
PF: 30
PS: 15

Layer Notes:
87-52cm: Problematic layer



Notes: