Wolf Creek - Spooner N
San Juan Range
CO
**Elevation:** 10933 ft
**Aspect:** 4°

Andrew Pierce
03/01/2022 - 11:43am
**Co-ord:** 37.46015N, -106.76717E
**Slope Angle:** 31°
**Wind Loading:** no

**Stability:**
**Air Temperature:** 3°C
**Sky Cover:** CLR
**Precipitation:** NO
**Wind:** Calm

**HS:** 238
**PF:** 35

**Layer Notes:**
**86-97cm:** Problematic layer

**Specifics:** Pit dug in a Ski Area; Pit is representative of backcountry; Ski tracks on slope; We skied slope




**Notes:** Quick obs pit targeting specific layers. Not a full profile.

*Pronounced dust layer at 70-71cm down

*86-97: bigger and more defined facets (rounding), results with non-standardized tests found on this layer (prying columns after CT and ECT). This is likely the layer most of the AMu triggered avalanches broke on recently in this forecast zone. Layer has 4 "lemons"