east Mt. Henderson
Beartooths
MT
Elevation: 9377 ft
Aspect: 27°

Beau Fredlund
11/15/2022 - 1:00pm
Co-ord: 45.04886N, -109.92894E
Slope Angle: 26°
Wind Loading:

Stability:
Air Temperature:
Sky Cover: FEW
Precipitation: NO
Wind: W Light Breeze

HS: 90

Layer Notes:
50-45cm: Problematic layer

Specifics: Recent avalanche activity on different slopes; We skied slope



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
□	1			
●				
□	1			ECTX

Notes: Noted one recent, nearby slab avalanche. A NE aspect around 10,000'. Photo attached. Avalanche was in a heavily wind affected area, snowpit location was wind sheltere