Ridge above Edelweiss
Snake River Range
WY
Elevation: 9081 ft
Aspect: W
Specifics: Cracking

Lane Aasen
11/28/2022 - 12:00pm
Co-ord: 43.48770N, -110.97039W
Slope Angle: 12°
Wind Loading: no

Stability:
Air Temperature: -10.1°C
Sky Cover: OVC
Precipitation: S1
Wind: Calm

HS: 123

Layer Notes:
112-123cm: Problematic layer



Notes: Localized cracking on the ridgeline, small sluffs on slopes just over 30 degrees at the bottom of Edelweiss.