Millertime
Carson Range
NV
Elevation: 8554 ft
Aspect: NE

wendy antibus
12/12/2022 - 2:45pm
Co-ord: 39.32151N, -119.87424W
Slope Angle: 35°
Wind Loading:

Stability:
Air Temperature:
Sky Cover: CLR
Precipitation: NO
Wind: NW Moderate

HS: 90
PF: 60
PS: 30

Layer Notes:
20-0cm: failure plane
20-0cm: Problematic layer

Specifics: Pit dug in a Ski Area; Pit is adjacent to avalanche: crown; Cracking; Recent avalanche activity on similar slopes



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
+				
⊟	1-3			**20-0cm:** failure plane

Notes: Profile dug into a crack that extended from large avalanche in Millertime. HS in area varies from 80 - 160 cms.