Julie's Backside
La Sal Mountains
UT
Elevation: 11094 ft
Aspect:
Specifics: Cracking

Dave Garcia
12/12/2022 - 1:46pm
Co-ord: 38.46228N, -109.25011W
Slope Angle:
Wind Loading: no

Stability:
Air Temperature: -12°C
Sky Cover: OVC
Precipitation: S1
Wind: SW Light Breeze

HS: 92

Layer Notes:
37-28cm: Problematic layer



	Crystal Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
92–90					
90–80					
80–70					
70–60					
60–50					
50–40					
40–30	□	1.5			
30–0					2x ECTX

Notes: Pit dug in sheltered location. No wind loading at pit site. Plenty of loading occurring elsewhere today.