Jan 29 Trico E
San Juan Range
CO
Elevation: 11317 ft
Aspect: E
Specifics:

Amy Pertuz
01/29/2023 - 10:00am
Co-ord: 37.89697N, -107.71693W
Slope Angle: 30°
Wind Loading: no

Stability:
Air Temperature: 18°C
Sky Cover: OVC
Precipitation: NO
Wind: S Moderate

HS: 166
PF: 45
PS: 20

Layer Notes:
114-113cm: Jan 14 facet crust
114-113cm: Problematic layer



Notes: No results in CT or ECT, but and informal "32nd" tap (two extra hard taps) produced a propagating failure in small facets above the Jan 14th facet crust