SSV - Kain Meadows
Banff, Yoho and Kootenay
AB
Elevation: 2018 m
Aspect: W
Specifics:

Banff Visitor Safety
01/03/2023 - 12:00
Co-ord:
Slope Angle: 38°
Wind Loading:

Stability:
Air Temperature:
Sky Cover: OVC
Precipitation: S-1
Wind:

HS: 170

Layer Notes:
105-104cm: Avalanche failure plane
105-104cm: Problematic layer



Notes: Fracture line profile on crown of sz 2 skier remote from 25 m away on 230228 at 1430 hrs. Released on facets & surface hoar on a 1F melt freeze crust (15 cm thick). Nearby, where the HS was 90 cm we got CTE(10) down 25 cm on the same layer of fc/sh.