Trinity Lakes Incident
Boise Mountains
ID
Elevation: 7976 ft
Aspect: 90°

Ethan Davis
03/27/2023 - 2:00pm
Co-ord: 43.62743N, -115.45098W
Slope Angle:
Wind Loading: previous

Stability: Fair
Air Temperature:
Sky Cover: FEW
Precipitation: NO
Wind: W Light Breeze

HS: 340

Layer Notes:
336-305cm: Snowfall after the incident
170-168cm: Suspected (2/18) layer
170-168cm: Problematic layer

Specifics: Pit is adjacent to avalanche: other; Recent avalanche activity on similar slopes; Recent avalanche activity on different slopes; We skied slope

[More Pit Specifics below]



Notes: Additional Pit Specifics: Snowmobile tracks on slope