Highroller Hangfire
Treble Cone
New Zealand
Elevation: 1971 m
Aspect: E
Specifics: Pit dug in a Ski Area

Sven Gorham
11/07/2023 - 10:00
Co-ord: -44.63232N, 168.87458E
Slope Angle: 42°
Wind Loading:

Stability:
Air Temperature: -3.3°C
Sky Cover: CLR
Precipitation: NO
Wind: Calm

HS: 93
PF: 1
PS: 1

Layer Notes:
52-28cm: Problematic layer



Notes: Pit dug in hangfire of controlled path that stepped down to same MFrc at ECT
ECT fractured above and below the 230625 crust on the same tap.
Upper pack very supporting and bridging strength across the top of the path.