Hlíðarfjall, Kulusukk
Tröllaskagi
Iceland
Elevation: 840 m
Aspect: SE

David Stöckel
07/11/2023 - 10:22
Co-ord: 65.65916N, -18.24503W
Slope Angle: 40°
Wind Loading: previous

Stability: Fair
Air Temperature: -3.5°C
Sky Cover: FEW
Precipitation: NO
Wind: Calm

HS: 150
PF: 0
PS: 0

Layer Notes:
90-92cm: Problematic layer

Specifics: Pit is adjacent to avalanche: crown; Collapsing, widespread



Notes: the avalanche fell likely in the morning of 06.11.23 or the night before, wile loading was still happening.