Shot 12	Nate Fuller	**Stability:** Fair	**HS:** 100	**Layer Notes:**
Teton Range	11/27/2023 - 2:00pm	**Air Temperature:**	**PF:** 100	**26-20cm:** Problematic layer
WY	**Co-ord:** 43.60279N, -110.85307W	**Sky Cover:**	**PS:** 15	
Elevation: 9300 ft	**Slope Angle:** 31°	**Precipitation:**		
Aspect:	**Wind Loading:** yes	**Wind:**		

Specifics: Pit dug in a Ski Area; Pit is representative of backcountry; Collapsing, localized; Cracking; Recent avalanche activity on similar slopes



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
V	3-5			
⊟	1			
⊟	1			ECTN8 @88cm
⊟	0.5-1			
□ (◎◎)	1-2			ECTP14 @30cm
□	2-3			
□	2			
⊟	2			

Notes: ECTP14 @30 failed on top of and through decomposing crust (30-26cm). Slab was a drift in the starting zone and very isolated.