Nak Shoulder
Cascades - Coquihalla
BC
Elevation: 1850 m
Aspect:
Specifics: Cracking

Dynamic Avalanche Technicians
02/12/2023 - 13:00
Co-ord: 49.60352N, -121.08961W
Slope Angle: 36°
Wind Loading: yes

Stability: Good
Air Temperature: -4.2°C
Sky Cover: BKN
Precipitation: S1
Wind: SW Moderate

HS: 61
PF: 40
PS: 20

Layer Notes:
27-22cm: No SH found in this spot
27-22cm: Problematic layer
14-0cm: early Nov crust



Notes: Numerous 2m cracks and <10 5-10m cracks off the ski tips. Mainly in freshly wind-loaded spots near the ridge top.