D Glade Hi
San Juan Range
CO
Elevation:
Aspect:
Specifics: Pit dug in a Ski Area

Travis Laverty
12/04/2023 - 12:00pm
Co-ord:
Slope Angle:
Wind Loading:

Stability:
Air Temperature: -2°C
Sky Cover: CLR
Precipitation: NO
Wind: Calm

HS: 70
PF: 70
PS: 40

Layer Notes:
70-50cm: 12/2
50-40cm: 11/25
40-10cm: 11/20
10-0cm: October Facets



Notes: