Ophir Pass
San Juan Range
CO
Elevation: 11300 ft
Aspect: SE
Specifics: Collapsing, localized

Krista Beyer
12/04/2023 - 2:00pm
Co-ord: 37.84731N, -107.76268W
Slope Angle:
Wind Loading:

Stability:
Air Temperature:
Sky Cover: FEW
Precipitation: NO
Wind: NE Calm

HS: 65
PS: 10

Layer Notes:
15-13cm: Problematic layer



Notes: Pit dug for baseline information. Looked for a location with a melt freeze crust to test reactivity and observe shear quality.