Musher
Rockies
BC
**Elevation:** 1990 m
**Aspect:** SW
**Specifics:**

Justin Clarke
08/12/2023 - 14:41
**Co-ord:** 52.74931N, -119.58874W
**Slope Angle:** 24°
**Wind Loading:** previous

**Stability:**
**Air Temperature:** -6.4°C
**Sky Cover:** BKN
**Precipitation:** S-1
**Wind:** S Light Breeze

**HS:** 90
**PF:** 69

**Layer Notes:**
**55-54cm:** 8-10mm SH
**55-54cm:** Problematic layer




| Form | Crystal Size | Moisture | ρ kg/m³ | Stability tests & Layer comments |
|---|---|---|---|---|
| | | | | |
| | | | | CT12, RP @76cm |
| | | | | CT11, RP @76cm |
| | | | | |
| V | 8 | | | CT20, SP @55cm DEC 1st SH Layer |
| | | | | 55-54cm: 8-10mm SH |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

**Notes:** Condition check—good but thin ski quality.