Black Face Adjacent
San Juan Range
CO
Elevation: 11960 ft
Aspect: E
Specifics: Collapsing, widespread; Collapsing, localized

Jason Habib
12/10/2023 - 11:25am
Co-ord: 37.82197N, -107.95064W
Slope Angle: 20°
Wind Loading: previous

Stability: Poor
Air Temperature:
Sky Cover: BKN
Precipitation: S-1
Wind: SW Light Breeze

HS: 62

Layer Notes:
10-0cm: Problematic layer



Notes: