Tin Cup Creek Meadows
Teton Range
WY
Elevation: 7125 ft
Aspect: SW
Specifics: Collapsing, widespread; Poor pit location

Glenn Browning
12/08/2023 - 12:00pm
Co-ord: 43.85085N, -110.95282W
Slope Angle: 12°
Wind Loading: previous

Stability:
Air Temperature: -10°C
Sky Cover: OVC
Precipitation: S-1
Wind: SW Calm

HS: 77
PF: 45

Layer Notes:
45-35cm: Problematic layer



Notes: Collapsing of snowpack with every step in meadows approaching the uphill trail to Green Mountain. Based on collapsing, CT scores, expected ECTP with low scores??
Choose to tour around creek