Cabin Bowl Crown
San Juan Range
CO
Elevation: 12100 ft
Aspect: NE

Dustin Eldridge
02/15/2018 - 11:00am
Co-ord:
Slope Angle: 36°
Wind Loading:

Stability:
Air Temperature:
Sky Cover:
Precipitation: S-1
Wind:

HS: 200

Layer Notes:
15-0cm: Chains. Intermittent crust
15-0cm: Problematic layer

Specifics: Pit dug in a Ski Area; Collapsing, localized; Cracking; Recent avalanche activity on different slopes



Notes: Hasty crown profile mid-route. Cabin Right. HS-AEr-R2-D2.5-G 3'x100'x1,000'. Slide stepped down on the upper track and released a slab on the left side of the track.