Lolo Pass HWY 12
Bitterroot
MT
Elevation: 5600 ft
Aspect: 75°

Logan King
02/18/2018 - 8:00am
Co-ord: 46.62733N, -114.58149W
Slope Angle: 20°
Wind Loading: yes

Stability: Very Poor
Air Temperature: -6.5°C
Sky Cover: BKN
Precipitation: S1
Wind: SW Moderate

HS: 245
PF: 75

Layer Notes:
166-162cm: Problematic layer

Specifics: Collapsing, widespread; Cracking; Recent avalanche activity on different slopes



Notes: Entire slope whumphed when exiting the pit. Whumphs and collapses were occurring on all aspects and elevations seen today. Small soft natural storm slabs were also observed (~1ft deep)