Rindabotn
Indre Sogn
Norway
Elevation:
Aspect:
Specifics: Pit dug in a Ski Area

Sander Buene
18/04/2018 - 11:50
Co-ord: 32V 390632W 6797275N
Slope Angle:
Wind Loading: no

Stability:
Air Temperature:
Sky Cover: BKN
Precipitation: NO
Wind:

HS: 180

Layer Notes:
70-69cm: Problematic layer



Notes: