Tushers
Southwest Utah
UT
Elevation: 10300 ft
Aspect:
Specifics:

Todd Leeds
01/08/2017 - 11:00am
Co-ord:
Slope Angle: 20°
Wind Loading:

Stability:
HS: 50
Air Temperature:
Sky Cover:
Precipitation:
Wind:

Layer Notes:
0-1in: dense
1-2in: Crust 1
2-3in: damp
2-3in: Problematic layer
3-4in: Supportable
[More Layer Comments below]



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
+				**0-1in:** dense
■				← ECTPV @2in Crust above failed
+				**1-2in:** Crust 1
■				**2-3in:** damp
□				**3-4in:** Supportable
				4-10in: Faceting
●				
●				
●				
□				**45-50in:** Facets, rounding

Notes: . Additional Layer Comments: 10-4in: Faceting; 50-45in: Facets, rounding;