Glory Exp's #2 & #3
Teton Range
WY
Elevation: 9756 ft
Aspect: NE
Specifics: Ski tracks on slope

Brenden Cronin
12/06/2022 - 2:15pm
Co-ord:
Slope Angle: 34°
Wind Loading: previous

Stability: Fair
Air Temperature: -10°C
Sky Cover: FEW
Precipitation: NO
Wind: S Light Breeze

HS: 65

Layer Notes:
13-11cm: Problematic layer



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
⊖ (⅄)	1 (3)			
⊖	1-2			
				STM @0cm
				ECTPV @0cm

Notes: Observers: D. Lawless & B. Cronin
Pit dug 10 M above Exploders #2 and #3.