West of Bald Mtn Pass
Uinta Range
UT
Elevation: 10420 ft
Aspect: 0°
Specifics:

Mark Staples
01/23/2018 - 1:00pm
Co-ord: 40.68051N, -110.91094W
Slope Angle: 27°
Wind Loading:

Stability: Good
Air Temperature:
Sky Cover:
Precipitation:
Wind:

HS: 102
PF: 102

Layer Notes:
11-0cm: mix of DH and crusts



Notes: Step off the sled and you sink to the ground. It's amazing how there's just enough supportability for the sleds to stay on top. ECTX because the snowpack just crumbles beneath the shovel. In this sheltered spot, it's weak but stable. Add wind-loading and it becomes unstable fast.