


West Lime Cr 1/13/17
San Juan Range
CO
Elevation: 10000 ft
Aspect: 70°
Specifics: Recent avalanche activity on different slopes

Susan Hale
01/13/2017 - 1:00pm
Co-ord:
Slope Angle:
Wind Loading: previous

Stability: Fair
Air Temperature: -3°C
Sky Cover: OVC
Precipitation: S-1
Wind: SW Light Breeze

HS:200
PF: 40
150-140cm: Problematic layer
110-0cm: shallow basal facets bottom

Layer Notes:



Notes: This is a benched but very lengthy highway avalanche path - a long stretch of hwy exposure. It is generally a planar slope but with undulations that cross load with southerly winds. This path has gained unusual volume this winter. The mid-pack is stout. Feel the upper-most instabilities will heal with time. This pit confirms that any future issues with this path will be with mostly storm snow