

2015 Fracturing

Sakshi Sharma

Stability:

HS:235

Layer Notes:

himalayas

02/03/2015 - 06:30

Air Temperature:

27-0cm: Problematic layer

India

Co-ord: 32.75500N, 77.26025E

Sky Cover:

Elevation: 3800 m

Slope Angle: 33°


Precipitation:

Aspect:

Wind Loading:

Wind:

Specifics: Cracking; Instability rapidly rising; Poor pit location



Form	Crystal Size	Moisture	ρ kg/m ³	Stability tests & Layer comments
•	0.5			
			0.12	
•	0.5-1	D		
			0.15	
•	1.5	D		
			0.15	
◻	0.5-1	D		
•	0.5	D		
			0.2	
•	0.5			
			0.25	
			0.35	
•	1	D		
			0.3	
•	1-2			
			0.3	
•	1-2	D		
			0.38	
•	0.5-1	D		
			0.3	
•	2	D		
			0.35	
•	2-3	D		
			0.4	
◻	2-3	D		
			0.38	
◻	4-5	D		
			0.25	
^	6	D		

Notes: